

**TABLE 5: LIST OF TANKS IN THE PRODUCT STORAGE TERMINAL**

**PST TANKAGE STATUS REPORT AS OF SEPTEMBER 2004**

Tank #	Product	Nominal Capacity (BBL)	Foundation Apron	Shell	Roof	Stairs	Guard Rails	Intercon Walkway	Floor	Remarks
1	AGO	80,500	OK	OK	OK	OK	OK		OK	Repaired & recalibrated. In service.
2	ATK	5,000	Repaired	OK	OK		OK		No apparent leak	Discharge valve repaired OK. Recalibrated & ready to receive product
3	Empty	10,000	OK	OK	OK	OK	OK		Repaired	To be repaired for Fire Water Storage
4	Empty	5,000	Damaged	Shell/Bottom corroded	Damaged	Corroded	Heavily corroded		Leaks. Needs replacement	
5	AGO	30,000	Below grade	OK	OK	OK	OK		No apparent leak	Apron to be refurbished Apply cold welds and repair
6	PMS	30,500	Below grade	Few bullet holes	OK	OK	OK		No apparent leak	Aporn Line Bleeding System.
7	PMS (Down)	30,500	Repaired	OK	OK	OK	OK		Repaired	OK. Recalibrated & ready to receive product.
8	PMS	15,000	Below grade	OK	OK	OK	OK		No apparent leak	OK
401	Empty	48,500	Good	Repaired	OK	OK	OK		Repaired	Repaired & recalibrated. In service.
402	JET-A1	23,800	Repaired	Repaired	OK	OK	Repaired	Repaired	Repaired	Repaired, epoxied & recalibrated. Ready to receive JET-A1.
403	AGO	10,000	Partially eroded	OK	OK	OK	OK	OK	No apparent leak	Apply cold welds to bullet holes on 6th shell. Experiences drops.
404	AGO	15,000	Partially eroded	OK	OK	OK	OK	OK	No apparent leak	Repair apron.
405	JET-A1	10,000	Partially eroded	OK	OK		OK	OK	No apparent leak	OK. Recalibrated.
406	ATK	10,000	OK	Few holes on 9th shell	OK		OK	OK	No apparent leak	OK. Recalibrated.
407	PMS	10,000	OK	OK	OK		OK	OK	No apparent leak	Cold weld applied to hole. Replace entire roof.
408	PMS (Down)	10,000	OK	Few holes on 8th shell	Completely corroded	Few corroded	Corroded	OK	No apparent leak	Remove water for internal inspection.

**9 tanks used for 244,500 BBL**

84300  
244500